

Mission BX6844 Mission Date 07 JAN 68 H-hour 07/0210Z L 1110L L 07/0610Z 1510L

Key Personnel	DCOW Personnel	Duty Hours	APT Picture Schedule		
Primary Pilot			Sat	Acq T	Avlb T Coverage
		06/08-16 L; 07/06-18 L	E6	0753	0813 PWAK
None		06/16-07/03 L; 1 - L	E6	0941	1001 RODN
Commander		06/06-13 L; 07/03-13 L	N2	1051	1111 RODN
TTFC		06/11-24 L; OFF	E6	1135	1155 TGT
Remarks		07/00-11 L; 1 - L	N2	1240	1300 RODN TGT?
25X1A 25X1A		06/00-11 L; 07/11-21 L			
25X1A		Standby period Contact			
		07/1310-1510L			

H-Minus	Action	25X1A	SOP	Rspbl Indiv	Time Due (Z)	Done (L)	Intls
-27:00	Start this checklist		B-3	C	2310	0810	JY
-26:00	Arrange work schedule		B-4	A	0010	0910	JY
-25:00	Determine APT picture schedule for mission day		B-10	C	0110	1010	JY
-23:30	Attend Commander's Briefing		B-1	A	0240	1140	JY
-23:00	Receive (Preliminary Operational Data)		B-1	A	0310	1210	0655 JY
Vrbl	Receive Wx Scout call signs		B-22	A	Vrbl	Vrbl	
	Determine TTFC preliminary briefing schedule		B-2	C	0100	1000	JY
	Prepare planning forecast & briefing slides for TTFC		B-2	C	0130	1030	JY
	Give preliminary briefing to crews		B-2	A	0400	1300	DEB
	Give preliminary briefing to crews		B-2	A	0500	1400	DEB
	Get TTFC mission briefing times for this checklist		B-2	A		1525	DEB
-21:00	Receive Mission Weather Data)		B-6	A	0510	1410	1320 DEB
-21:00	Receive (Terminal Forecasts)		B-5	A	0510	1410	1320 DEB
-20:00	Prepare briefing acetate on wall map		B-7	A	0610	1510	1530 DEB
Vrbl	Receive (Composite Route Data via data link)		B-6	A or B	Vrbl	Vrbl	1755 DEB
-17:30	Receive Amnd (Mission Weather Data update)		B-6	B	0840	1740	1700 DEB
-17:15	Receive (Terminal Forecasts update)		B-5	B	0855	1755	1730 DEB
-17:00	Receive Primary Alternates & Missed AR Bases		B-21	B	0910	1810	0940 DEB
-17:00	Give initial briefing to pilots & operations staff		B-7	B	0700	1600	1600 DEB
-15:00	Receive (Tanker Mission Weather Data)		B-9	B	1110	2010	1908 DEB
-14:00	Prepare route winds slide & ready others for TTFC		B-24	B	1210	2110	2110 DEB
	Turn on TTYs needed for monitoring & plotting		B-12	X	1200	2100	2100 DEB
	Receive (Final Operational Data)		B-8	B	1400	2300	2338 DEB
-11:00	Prepare RODN & top-off AR forecasts		B-5	B	1510	0010	0010 DEB

BLACK SHIELD CHECKLIST  
(as of 23 Dec 1967)Mission **BX6844**  
Msn Date \_\_\_\_\_H-hr / Z L ATD L  
L-hr / Z L ATA L

Page 2 of 2

H-Minus	Action	SOP	Rspbl Indiv	Time Due (Z)	Done (L)	Intls
25X1A -10:00	Send [ ] Terminals & Top-Off AR Forecasts]	B-5	B	1610	2110	0035
-9:00	Give [ ] [Wx effect on launch] to Msn Coord	B-23	B	1710	0210	0030
-9:00	Receive [ ] [Go/No Go Weather Forecasts]	B-11	B	1710	0210	0128
-8:30	Prepare met watch log forms for use in CP	B-12	Z	1740	0240	0235
-8:30	Complete slides & prepare flimsy masters for TIFC	B-24	B	1740	0240	0230
	Plot 1200Z RODN & AR vicinity RAOBs	B-12	Z	1800	0300	0245
25X1A	Plot [ ] & any pertinent 30mb data on map for fcstr	B-12	Z	1900	0400	0245
-8:00	Send [ ] Hazardous Wx Advisory] if needed; thru L-hr	B-16	A,B,C	1810	0310	Comp 0340
-7:30	Appraise TIFC slides & flimsy masters; run off copies	B-24	C	1840	0340	
	Give TIFC mission briefing & 175 data to: (Top-Off AR wx scout & spare) [ ]	AR B-24	C	2045	0545	
25X1A	(1st cell, distant AR) [ ]	AR B-24	C	2105	0605	
	(2nd cell, distant AR) [ ]	AR B-24	C	—	—	
	(Top-Off primary) [ ]	AR B-24	C	2300	0800	
	(Other AR, strip alert, etc.) <i>Strip alert, if needed</i>	B-24	C	0315	1215	
-5:00	Prepare RODN & Top-Off AR forecasts	B-5	C	2110	0610	
25X1A -4:00	Send [ ] Terminals & Top-Off AR Forecasts]	B-5	C	2210	0710	
-4:00	Send [ ] Met Watch Observations]	B-18	Z	2210	0710	
-3:45	Plot 1800Z RODN & AR RAOBs, temp dev, 30mb data on map	B-12	Z	2225	0725	
-3:45	Appraise late data, FIREPs; complete wall map overlay	B-20	A	2225	0725	
-3:40	Take overlay, temp dev, msn folder, etc. to brfg room	B-20	A	2230	0730	
25X1A -3:30	Brief pilots & operations staff	B-20	A	2240	0740	
-3:00	Receive [ ] Amnd [Go/No Go Weather Forecasts]	B-11	A	2310	0810	
-2:30	Begin met watch log; post AR board & color tags in CP	B-12	Z	2340	0840	
25X1A -2:30	Get letdown plates at briefing, add wx, give to DCOM	B-14	A	2340	0840	
-2:00	Receive & post [ ] [Wx Scout Reports] (bad news only)	B-22	A	0010	0910	
Vrbl	Receive APT pictures; deliver to CP for appraisal	B-10	C	ASAP	ASAP	
-1:10	Rebrief pilots if necessary	B-20	A	0100	1000	
25X1A -1:00	Begin met watch in CP	B-13	A	0110	1010	
Vrbl	Discuss APT picture with Hq SWO (HY-2, psbl [ ])	B-10	A			
H+0:30	Prepare debriefing form (draw route, enter data, etc.)	B-15	A	0240	1140	
*****						
L+0:15	Return materials from CP to weather station	B-13	X			
L+0:15	Complete debriefing form entries (landing ob, times)	B-15	A			
25X1A L+0:45	Attend pilot debriefing	B-15	A			
ASAP	Coordinate [ ] input with DCOM after debriefing	B-15	A	ASAP	ASAP	
	Clean briefing overlays, put weather station in order	B-12	X	1100	2000	

Leave completed checklist, debriefing form, met watch log, and all other material pertaining to the mission in the mission folder. After checking for completeness, put the folder in a manila envelope marked "BX6844 Wx File" and file in safe. When no longer needed for reference, turn over to Intelligence for storage.

25X1A ZCZC764

\*\*\*\*\*642/061829Z ZFR-1 ZFO [REDACTED]

BT 25X1A

XXXXX 25X1A

[REDACTED] 453

[REDACTED] 857

25X1A

25X1A

T O P S E C R E T 061829Z CITE [REDACTED] 6150

FLASH [REDACTED] INFO PRIORITY [REDACTED]

[REDACTED] 90

25X1A

25X1A

A. BX6844

B. MISSION GO-NO-GO MSG

C. CANCELLED DUE WX

D. NONE

T O P S E C R E T

BT

NNNN

06/1840 Z  
0340 I  
Jh

25X1A

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

Next 3 Page(s) In Document Exempt

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

25X1A

ZCZC 759FTX388

/061746Z ZFF1 ZPO [REDACTED]

BT

XXXXXX

25X1A

OPCEN 831 [REDACTED] 791

27144

25X1A

TOP SECRET 061744Z CITE WENT 17

25X1A

IMMEDIATE [REDACTED]

[REDACTED] COR

A. BX 6844

B. VLD: 07/0330Z TO 0530Z JAN 68

C. THRU E. NO CHANGE

F. 1928 WILL BE AVAILABLE FOR TELCOM AT 07/0205Z.

TOP SECRET

BT

NNNN

25X1A



6 JAN 68 18 27 Z

NNNTB VT

KTW

AZCZC755FTX3

7251112 2011 115 COLD

BT

XXXXX

OPCEN 829 [REDACTED] 738

27412

25X1A

25X1A

TOP SECRET 061614Z CITE WEDON 677

25X1

IMMEDIATE [REDACTED]

A. BX 6844

B. VLD: 07/0330Z TO 0530Z JAN 68

C. CAT ONE AND TWO IN SC WEST OF 2189 21200 211/505 21207  
21408 21607 21905 22103 22301 22501. CAT THREE IN SC 21806  
21907 22007 22107 221506 22105/5 21905/5 21806 CAT THREE IN  
SC SOUTH OF 21009 21512 21315 22022 22022 21517 21017 REMAINDER  
CAT FOUR AND FIVE.

D. N/A

E. NO SIG CHANGE

F. FRONTAL SYSTEM FROM 01 SOUTH OF OKINAWA TO 25N 105E WITH  
DETERIORATING WEATHER EXTREME NORTH EAST VIETNAM WILL START  
CLEARING BEHIND FRONT AFTER 06/03Z BUT ONLY TO 20.5N AND 106E.  
REMAINDER WILL CONTINUE CAT FOUR OR FIVE.

TOP SECRET

BT

06/1628Z  
0138 I JL

25X1

NNNN

25X1A

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

Next 1 Page(s) In Document Exempt

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

NNNN

WECEN SEZ

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

WECEN SEZ WILL BE A WHILE WILL GET IT ASAP

THOUGHT IT CAME FROM WECEN

CP HERE SEZ WILL BE SENT WHEN

INFO AVAILABLE ARZCZC747

029/061430Z ZFF-1

BT

XXXXX

25X1 WECEN 196 [REDACTED] 449

25X1 TOP SECRET 061429Z CITE [REDACTED]

25X1 IMMEDIATE WECEN [REDACTED]

A. BX6844

B. 7/0330Z TO 0530Z JAN 68.

25X1 C. NO CHANGE FOR [REDACTED]

25X1 D. [REDACTED] ARCP CHANGED TO 07/2409Z. REST SAME.

E. THRU F. NO CHANGE.

25X1 G. FILE IMMEDIATE [REDACTED] MLI 06/1510Z. [REDACTED]

25X1 MLI 06/2210Z. [REDACTED] INCLUDE [REDACTED] A/R FCST ON [REDACTED]

H. WECEN: PLEASE ADVISE WHEN 407 PASS 1928 AVAILABLE FOR TELCOM  
READOUT. CONTINUE ALERTS UFN.

TOP SECRET

BT

25X1

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

23382 [Signature]



Next 5 Page(s) In Document Exempt

NNNN

6 JUN 68 07 13Z

/060741Z ZFFI ZFO [REDACTED]

BT

YXXXX

25X1A

[REDACTED] 785 OPCEN 826

TOP SECRET 060730Z CITE WEED 0748

IMMEDIATE [REDACTED]

25X1A

[REDACTED] AMND

A. BX6344

B. VLD 07/0330Z TO 0530Z JAN 68.

C. CAT ONE PATCHY TWO IN CU/CI WEST OF 22503 222.5/02.4

22003 21706 21401 21303 21207 211.4/06 21204 21201 21097. CAT  
THREE PATCHY TWO IN SC/CI WEST OF 222.5/02.4 22203 22206 22008  
21908

2100 21807 217.5/06 21706 CAT THREE PATCHY TWO IN CU/CI SOUTH  
OF 21009 21512 21315 22021 21923 21522 21022. RMDR OF AREA CAT  
FOUR AND FIVE.

D. NO CHANGE FROM [REDACTED]

E. DATA INDICATE CONDITION STARTING TO DETERIORATE. SOUTH-  
ERLY FLOW AT LOW LEVELS DURING VLD PERIOD TO SHIFT SOUTH-  
EASTERLY AFTER VLD TIME BRINGING CLOUDS AND CLDS OVER ALL OF  
NVN.

TOP SECRET

BT

0800Z  
[Signature]

25X1A

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

Next 1 Page(s) In Document Exempt

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

TOP SECRET 060400Z CITE WECEN 6765

25X1  
IMMEDIATE

25X1A

A. BX6844

B. 07/0330Z TO 0530Z JAN 68

C. CAT ONE PATCHY TWO IN CU/CI WEST OF 22503 222.5/02.4 22003 21706  
21408 21308 21207 211.4/06 21204 21201 21297. CAT THREE PATCHY  
FOUR IN CU/AC/CI NORTH OF 22503 222.5/02.4 22003 21706 21806  
21905 220.5/04.5 222/05.5 22407 22508. CAT TWO IN SC WITHIN  
22508 22407 222/05.5 220.5/04.5 21905 21806 21607 21908 22109  
22509. CAT THREE VRBL TWO IN CU/CI SOUTH OF 21009 21512 21315  
22021 21923 21522 21022. RMNCH CAT FOUR AND FIVE

D. A/R FCSIS

25X1  
NO SIG CLD 10 MI 270/75 M31 OCNL LGT TURB 380/570  
4/8 CI 300/340 RPT 070/10 M31 NIL 380/650

E. WEAK UPPER TROP TO WEST WITH INCREASING MOISTURE TO INCREASE CLDS  
WEST NVN. SSW LOW LEVEL FLOW TO BRING OVERCAST CONDITIONS TO  
SOUTH CHINA.

TOP SECRET

BT

25X1A

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5

Next 3 Page(s) In Document Exempt

Approved For Release 2002/08/06 : CIA-RDP69B00041R002600040002-5